

SECTION V - HEALTH HAZARD DATA

THRESHOLD LIMIT VALUE

LD50 Rat Oral >1.0 gm/kg estimated. Rabbit Percut LD50 >2.0 gm/kg estimated.

EFFECTS OF OVEREXPOSURE

DANGER! Prolonged or repeated contact of liquid or breathing of vapor or mists may cause delayed or serious injury.

EMERGENCY AND FIRST AID PROCEDURES

Wash skin immediately with soap and water. Flush eyes immediately with plenty of water. Get medical attention. Contaminated clothing and shoes should be washed before using again.

SECTION VI - REACTIVITY DATA

STABILITY

UNSTABLE

CONDITIONS TO AVOID

STABLE

X

INCOMPATIBILITY (Materials to avoid)

Strong acids, bases and certain metallic salts

HAZARDOUS DECOMPOSITION PRODUCTS

CO₂, Aldehydes, Acids

HAZARDOUS POLYMERIZATION

MAY OCCUR

CONDITIONS TO AVOID

WILL NOT OCCUR

X

Will exotherm in small quantities

when combined with Part A

SECTION VII - SPILL OR LEAK PROCEDURES

STEPS TO BE TAKEN IN CASE MATERIAL IS RELEASED OR SPILLED

Remove excess. Clean residue

with solvent.

WASTE DISPOSAL METHOD

Landfill or controlled burning as regulated by all

governmental agencies.

SECTION VIII - SPECIAL PROTECTION INFORMATION

RESPIRATORY PROTECTION (Specify type)

Approved NIOSH respirator and mask*

VENTILATION

LOCAL EXHAUST

Highly recommended

SPECIAL

MECHANICAL (General)

Highly recommended

OTHER

Protective clothing

PROTECTIVE GLOVES

Rubber

EYE PROTECTION

Safety goggles

OTHER PROTECTIVE EQUIPMENT

*This is not necessary unless the cured adhesive is dry sanded, abraded, etc.

See Section II

SECTION IX - SPECIAL PRECAUTIONS

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORING

Store at 75°F. Keep containers closed.

OTHER PRECAUTIONS

Read container label

ANSI Classification 6